


Stanley old style lock on MC521

Attachment 3

MC521 Terminal Block Connections — TB1 through TB5

(Sheet 1 of 1)



* These are


Polarized -

I might have

Drawn them

Backwards -

* REMOVE IF EXTERNAL POWER SUPPLY IS USED.



Add San Automating Inc